This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.

App No.: Not Yet Assigned Inventor: Gebhard Melcher

Docket No.: 20046/0200828-US0

Sheet 1 of 5




FIG 2

CLKIN 3

Q2N

Q2N

Q2N

Q1

Q1N


Q1N

PRIOR ART

App No.: Not Yet Assigned Docket Inventor: Gebhard Melcher Sheet 2 of 5


Docket No.: 20046/0200828-US0

FIG 3 Tnovl Tnovl



PRIOR ART


FIG 4




App No.: Not Yet Assigned , Inventor: Gebhard Melcher

Docket No.: 20046/0200828-US0

Sheet 3 of 5






App No.: Not Yet Assigned Inventor: Gebhard Melcher

Docket No.: 20046/0200828-US0

Sheet 4 of 5



App No.: Not Yet Assigned Inventor: Gebhard Melcher

Docket No.: 20046/0200828-US0

Sheet 5 of 5

